

# **School Facility Score Summary 2022-2023**

Scoring Sections	100% Section A	80% Section B
Maximum # of Compliant Questions:	25	34

100% Section A Compliance	Score	NJQSAC FISCAL DPR [All items are in compliance in building(s)]
# of <b>No</b> responses in section A	0	Compliant (No Exceptions)
# of No responses in section A		Non-Compliant (Corrective Action Needed)

80% Section B Compliance	Score	NJQSAC DPR [At least 80% of items are in compliance in building(s)]
A. Number of <b>Yes</b> responses	25	
B. Number of <b>No</b> responses	0	Compliant Line (A) is equal to or greater than Line (D)
C. Subtotal [A + B ]	25	
D. Multiply [( <b>C</b> ) × 80%]	20	Non-Compliant Line (A) is less than Line (D)

	LEA Assura	nce Signatures	
School Facility Name: Hurden Looker	·		
Completed By Cal	aft )	Title <i>CEFM</i> 1	Date
David DeFluri		Date 10 – 20 - 2022	
Certified Educational Facilities Mana	ger Jif position used by	/ district)	
Chief School Administrator		Date/0/27/2	2

### Health and Safety Evaluation Of School Buildings Checklist 2022-2023

County: Union	District	Occupying Building: Hillside	
Leased [ ] or Own	ed [ x] School Building Name:	Ola Edwards Community - GW	
Completed By:	David DeFluri , CEFM	Date: 10 - 20 - 2022	

This form shall be used for the evaluation of school buildings (pursuant to 6A:26 6.1 and 6A:26 8.1) Traditional Public School Districts (owned or leased), Private Schools for the Disabled, Charter Schools, Renaissance School Projects and any other setting used for instruction. This evaluation checklist shall be completed annually by appropriate district personnel and kept on file for inspection or other legal issues. These indicators cover regulations issued by NJDOE, NJDCA, NJUCC, OSHA. The emphasis of this evaluation is for the health and safety of students and staff even in the absence of a specific Statute or Code. The items listed are not mutually exclusive of other findings a monitor/inspector may cite. See "Facility Checklist Instructions and Guidance" for additional information. (Items specific to Temporary Spaces are denoted with code . 6A:26-8.1)

#### Section A: 100% Items

(this section must have full compliance with items)

#### 100% Compliance

Current Licenses And Certificates #1 to #10	Yes	No	N/A	Violation Location
<ol> <li>A current certificate of compliance with the Uniform Fire Code has been issued by the local or State fire official/inspector within the year and posted in a conspicuous location. (or current abatement inspection is available)</li> </ol>	х			
2. A current inspection report of the local health official (kitchen, cafeteria, pool, etc.) is available.	Х			
3. A 3 year asbestos management plan, as required by A.H.E.R.A., is available including current 6 month surveillance letters. If constructed without asbestos, a letter of certification from the architect is available.	х			
4. An annual inspection report of the Department of Environmental Protection for the operation of a sewage treatment plant, where applicable, is available.			х	
5. Current boiler inspection certificate(s) posted at site of boiler.	X			
6. Current license(s) for high and low pressure boiler operators, as required by code, are properly posted.	х			
7. Current drinking water supply inspection reports are available to comply with the Safe Water Drinking Act. (N.J.A.C 58:12A-1) (6A:26-12.4)Also, evidence of testing of water for lead has been provided by the district through annual submittal of the Lead Testing Statement of Assurance.	x			
8. One fire drill and <i>one</i> school security drill are held each month; [See"Checklist Instructions" for Certificate of Assurance]18A:41-1	х			

	Yes	No	N/A	Violation Location
<ol><li>Right To Know requirements are properly posted and MSDS reporting materials on file for review.</li></ol>	х	200		
10. District has defibrillators identified with appropriate signage and made available in an unlocked location on school property, which is accessible during the school day and any other time in which a school-sponsored athletic event or team practice, in which pupils of the district are participating, is taking place and is within reasonable proximity of the school athletic field or gymnasium, as applicable (Janet's Law 18A:40-41a-41c)	x			
Exits/Exterior #11 to #12	Yes	No	N/A	Violation location
11. Exterior switches and receptacles are covered by securely fastened weather-proof plates and fixtures are securely mounted with no exposed wires.	х			
<ul> <li>12. All exterior exits are in good condition, locked from outside access; readily accessible and free of obstructions for use in an emergency; including:</li> <li>a. Fire escapes and/or exterior stairs can be safely negotiated. Exterior doors shall not be propped open.</li> <li>b. Panic hardware is provided on exit doors of all spaces with an occupancy load/capacity greater than 50.</li> </ul>	X			
Interior #13 to #21	Yes	No	N/A	Violation Location
13. All electrical outlets; switches, receptacles and junction boxes; electric wires; fuses and/or circuit breaker panels; etc. are properly covered and/or secured and/or protected.	Х			
14. Sufficient access and working space is provided and maintained around all electrical spaces. Items, especially combustibles, are a minimum of 36 inches from electrical power sources or equipment; i.e.: circuit breaker panels, fuse boxes, transformers.	х			-
15. Instructional areas are free of all unapproved construction; e.g.: walls; partitions; doors and stairs; etc.	х			
16. The hardware on doors of any space occupied by students shall permit egress from the room at all times. Key-operated locks, thumb-turn locks, hasps dead bolts, slide bolts or similar types of locking devices shall not be permitted. 6A:26-8.1 (d.1.i.2)	x	А		
17. Unobstructed vision panels with code approved glass are installed in doors opening into corridors. Interior glazing shall be safety glazing. 6A:26-8.1 (d.1.i.3)	Х			
18. Kindergarten and Pre-K toilet requirements are met. N.J.A.C.			X	
6A:26-6.3(h)4.				

Interior #13 to #21	Yes	No	N/A	Violation Location
20. Dangerous chemicals (i.e., liquefied petroleum gas/propan and/or explosive materials (i.e.: gunpowder; picric acid) are not stored/present in the building. If needed, flammable ar combustible materials are properly stored/maintained (i.e., properly rated cabinets; not in boiler room/hazardous areas	e nd in		X	
<ul> <li>21. Carbone Monoxide Detectors Must be in the vicinity of all fuel burning appliances. <ul> <li>Gas and oil heating systems: Boilers, Furnances, central and unitary equipment.</li> <li>Generators: portable and permanaent.</li> </ul> </li></ul>				
<ul> <li>Natural gas and propane appliances: Water heaters ranges, stoves, ovens, laundry washers and dryers</li> <li>Fireplaces</li> <li>Required in hallways connected to space with the source</li> <li>NJAC 5:70-4.3(a), NJAC 5:70-4.9(d) and NJAC 5:70-4.19 (d)</li> </ul>	, X			
Vocational/Laboratories #22 to #25	Yes	No	N/A	Violation Location
<ul> <li>22. Power machinery and equipment, as well as science labs, ha appropriate safety features in place, including as applicable</li> <li>a. Appropriate placement on the floor and required point of operation guards to protect users from injury due to moving parts.</li> <li>b. Clearly visible and accessible push-type emergency cut-of switches at appropriate locations within shops to deenergize electrical supply to nonportable machinery.</li> <li>c. Non-portable machinery provided with magnetic type switches to prevent automatic restart upon restoration of power after an electrical failure or reactivation of the emergency cut-off switch.</li> <li>d. Key-operated electric solenoid shut-off valves on natural gas lines in science laboratories and shops constructed after 1979. On all other gas lines there is an emergency shut off valve which is clearly marked and accessible.</li> </ul>	: of out		x	
<ol><li>At a minimum, one # 20 BC rated fire extinguisher is provide in each laboratory and vocational area.</li></ol>	d		x	
<ul> <li>24. Adequate eye and body protection is provided, including:</li> <li>a. Eye protection devices (glasses, goggles) for students and faculty in each laboratory and shop area, including appropriate provision for their sanitation.</li> <li>b. Emergency eyewash device(s), with 15 minutes continuo flow, where caustic or corrosive materials are used.</li> <li>c. An emergency cold-water shower for chemistry laborato if constructed after October 1985. (NJAC 6A:12.5)</li> </ul>	us		x	
<ul> <li>25. Room provides for proper local or general ventilation and/or exhaustion of toxic and/or dangerous fumes and/or odors, including for the following activities, as applicable:</li> <li>a. For science activities (i.e.: via fume hoods)</li> <li>b. For welding operations</li> </ul>			х	

。在1965年,1965年,1965年,1965年,1965年,1965年,1965年,1965年,1965年,1965年,1965年,1965年,1965年,1965年,1965年,1965年,1965年,1965年,

Vocation	onal/Laboratories #22 to #25	Yes	No	N/A	Violation Location	
c.	For paint spraying operations:  1 Auto: should have separate exhaust system.  2 Art: proper ventilation for spray/ paint with fumes					
d.	Art: Safe designated space/room for kilns with proper ventilation					
е.	For dust generating operations, such as wood working, (i.e.: a dust collecting system which should be either single or multi-use vacuum packs or a central dust collection system					
		Yes	No	N/A		
100%	Items Total	17	0	8		

## Section B: 80% Items

(Must be compliant with 80% of these items to pass along with corrective action on the non compliant items) 80% Compliance

Ex	its/Exterior #1 to #4	Yes	No	N/A	Violation Location
1.	<ul> <li>No evidence of major exterior building structural damage.</li> <li>Example(s) would include:</li> <li>a. Exterior walls appear free of structural cracks, loose masonry and crumbling parapets; lintels appear free of rust and flaking.</li> <li>b. Gutters and downspouts appear to be in good condition and are secured to the building; runoff does not appear to be obstructed or create drainage or soil erosion.</li> </ul>	х			
2.	All exterior receptacles are GFI protected in accordance with code.	х			
3.	All school grounds, including general purpose play areas and athletic fields, are free of holes; glass; stumps, roots; rocks and other hazardous obstacles. Fences are maintained and are free of holes. The outside physical education area for students shall include, but not be limited to, sufficient space, equipment, and safe surfaces for the temporary facility enrollment and program needs and be protected from hazards or traffic conditions. 6A:26-8.1(1.ix)	х		7	
4.	Playground area and equipment appear to be in safe operating condition and in compliance with code and district maintains documentation of compliance and regular (annual and/or monthly) inspections.	х			
Int	erior Items #5 to #26	Yes	No	N/A	Violation Location
5.	All interior exits and corridors are in good condition; readily accessible; and free of obstructions and/or excessive materials which would hinder exiting.	х			
6.	Emergency evacuation egress procedures are posted at a visible height and standard location in all areas. 6A:26-8.1 (d.1.i.4)	X			

Interior Items #5 to #26	Yes	No	N/A	Violation Location
<ol><li>Doors leading to interior courtyards are clearly marked: "Not an Exit."</li></ol>			X	
8. Handrails on both sides of interior stairways, guardrails, and interior stair treads are free of surface features which may cause injury and/or are properly secured. Interior stair treads do not show evidence of extensive wear and are generally in good repair.	х			
9. Stage curtains need to indicate flame proof or flame retardant and certificates are on file.	Х			
10. All education spaces shall be equipped with a communication devise/system connected to the main office and capable of emergency communication to local authorities or 9-1-1. 6A:26-8.1 (d.1.i.6)	х			
<ul> <li>11. Electric outlets and/or wiring appear appropriate, including:</li> <li>a. GFI protection for receptacle(s) within 6 ft of water in accordance with code.</li> <li>b. Electrical extension cords and surge protectors used appropriately, with extension cords only used for temporary need(s).</li> <li>c. Sufficient electrical duplex outlets shall be provided to satisfy the program needs as provided in N.J.A.C. 6A:26-6.3 6A:26-8.1(1.vii.2)</li> </ul>	X			
12. Nurse's Office: District boards of education shall provide the necessary facilities, equipment and supplies for the performance of the duties required under State law and the rules by health services personnel. (6A:26-12.3 & 6A:26-6.3(b))	Х			
13. Individual or central mechanical ventilation unit(s) are operating in all student and staff occupied rooms/areas and toilet facilities; air conditioners are operational in windowless interior areas. Heating and ventilation requirements shall be as set forth in N.J.A.C. 6A:26-6.3 and the UCC. 6A:26-8.1 (1.iii).	Х			<u> </u>
14. Lighting levels in all instructional areas at least 50 foot candles, as measured with a light meter, comply with code and lamps/bulbs are covered with a lens cover or equivalent protection. (6A:26-8.1(1.vi) & 6A:6.3(g)(1))	х			
15. Instructional areas have no unauthorized and/or potentially hazardous materials/equipment in rooms. 6A:26-8.1 (i1) Dangerous touch points in educational spaces should be covered such as hot pipes, radiators (see end of checklist copied from guidance document).	х			
6. A chalkboard or whiteboard, and/or display board is provided in each instructional space and is free of cracks and jagged edges. 6A:26-8.1 (1.vii.1)	X			
7. Ceilings, walls and floors are free of holes, sags, and evidence of water damage. The average ceiling height shall be at least 8' feet for instructional spaces in temporary facilities in an	x	g g		